## Message

From: Beslow, Mike [beslow.mike@epa.gov]

2/17/2017 12:55:20 PM Sent:

To: Dixit, Naeha [dixit.naeha@epa.gov]

FW: Wednesday, Feb 15th 2017 Outfall and sump inspection reports Subject:

Attachments: FROM IHWPQ204@arcelormittal.com.pdf

## fyi

----Original Message----

From: Barnett, Thomas R [mailto:Thomas.Barnett@arcelormittal.com]

Sent: Wednesdáy, February 15, 2017 4:04 PM
To: Fitzgerald, Sean F MST1 <Sean.F.Fitzgerald@uscg.mil>; Beslow, Mike <beslow.mike@epa.gov>

Cc: David Greinke (DGREINKE@idem.IN.gov) < DGREINKE@idem.IN.gov; nream@idem.IN.gov; Benoit, Simonne T

<Simonne.Benoit@arcelormittal.com>

Subject: Wednesday, Feb 15th 2017 Outfall and sump inspection reports

Engineering and Design started to move the three remaining Powerhouse sump discharges to the Ash Pit, and north to the Terminal Lagoon.

Thomas Barnett | Manager, Environmental Technology ArcelorMittal Indiana Harbor LLC. ArcelorMittal USA LLC

Environmental Department | 3001 Dickey Road, Sta. 001 East Chicago, IN 46312

T +219 399 2380 | M +219 313 1605 | F +219 399 3211 | www.arcelormittal.com

----Original Message----

From: ihwpq204@arcelormittal.com [mailto:ihwpq204@arcelormittal.com]

Sent: Wednesday, February 15, 2017 5:05 PM

To: Barnett, Thomas R < Thomas.Barnett@arcelormittal.com>

Subject: FROM IHWPQ204@arcelormittal.com

Please open the attached document. It was scanned and sent to you using a Xerox Multifunction Printer.

Attachment File Type: pdf, Multi-Page

Multifunction Printer Location:

Device Name: ihwpq204

For more information on Xerox products and solutions, please visit http://www.xerox.com